

Work Order

Number	2025-00000996	Request Date	1/24/2025 12:00:00 AM
Type	Water Inspection	Schedule Date	
Priority		Assign Date	
Requester	Amy Fernandez	Assigned To	Scott, William Brian
Account	143252-001	Service Address	183 SW SILVER PALM DR
	ADAMS HOMES OF NORTHWEST FL INC Phone:		LAKE CITY, FL 32024

Comments	201 NEW TAP. VERIFY THAT THEY CONNECTED TO THE WATER METER CORRECTLY. COLTON WITH BARRS PLUMBING CAN BE REACHED AT 386-984-5219 AF
----------	--

New Meter Device	Meter #99287116
	MXU #136313352

Read 0000010

Read

Amy 01/24/25

Read Date 01-24-2025

Read Date

2:00pm-3:00pm

Comments Meter and check valve installed properly
Meter right side of house builder on site

Completed By: Kap

Work Order

Number	2025-00000998	Request Date	1/24/2025 12:00:00 AM
Type	Sewer Inspection	Schedule Date	1/24/2025 12:00:00 AM
Priority		Assign Date	
Requester	Amy Fernandez	Assigned To	Scott, William Brian
Account	143252-001	Service Address	183 SW SILVER PALM DR
	ADAMS HOMES OF NORTHWEST FL INC Phone:		LAKE CITY, FL 32024

Comments	201 NEW TAP. VERIFY THAT THEY CONNECTED TO THE SEWER CORRECTLY. COLTON WITH BARRS PLUMBING CAN BE REACHED AT 386-984-5219 AF
----------	--

New Meter Device				

Read

Read

Amy 01/27/25

2:00pm-3:00pm

Read Date

01-24-2025

Read Date

___ / ___ / ___

Comments

Sewer line and clean out installed properly
Sewer line front left Builder on site

Completed By:

Kap