BLOWER DOOR TESTING, LLC



BPI ID# 5059955

COLUMBIA COUNTY BUILDING DEPARTMENT Blower Door Test Results Form

Date: 4/19/24	Permit Number:	48295
Job Address: 891 FAIRWAY DR.,	LAKE eity,	FL 32025
AIR INFILTRATION TEST RESULTS		
CFM (50) = 3/5		
Volume = 3648		
ACH (50) = CFH (50) X 60 / Volume = 5, 2	\PA	SS FAIL
CERTIFICATION OF TEST RESULTS		
R402.4.1.2 Testing. The Building or dwelling unit shall be test exceeding 7 air changes per hour in Climate Zones 1 and 2, at through 8. Testing shall be conducted with a blower door at shall be conducted by either individuals as defined in Section licensed as set forth in Section 489.105(3)(f), (g), or (i) or an of the test shall be signed by the party conducting the test a performed at any time after creation of all penetrations of the	and 3 air changes per hou a pressure of 0.2 inches on 553.993(5) or (7), Florid approved third party. A wind provided to the code of	or in Climate Zones 3 w.g. (50 Pascals). Testing la Statutes or individuals written report of the results official. Testing shall be
I hereby certify that the above Air Infiltration To	est results demonst	rate compliance with
Florida Energy Code requirements in accordance	e with the5th Editio	n 2014 Florida
Building Code-Energy Conservation R402.4.1.2.		
Testing Company Name: BLOWER DEOR	TESTING.	LLC
Tester Name: TAMES W. BEORGE	Lic./Cert.#: 5	059955
Tester Signature: James W. Hea	71/	
	0.	
135 NE Hernando Avenue, B-21		Phone: 386-758-1008

James W. George 7461 NW 113th ST. Chiefland FL 32626

Lake City, FL 32055

www.columbiacountyfla.com

BPI ID# 5059955

Fax: 386-758-2160