

CODE ENFORCEMENT
PRELIMINARY MOBILE HOME INSPECTION REPORT

1208-02

74

DATE RECEIVED 8/2 BY ILW IS THE M/H ON THE PROPERTY WHERE THE PERMIT WILL BE ISSUED? No

OWNERS NAME David Lomas PHONE 386-454-5301 CELL

ADDRESS 429 SW Buck Court Ft White FL 32038

MOBILE HOME PARK SUBDIVISION Lot 22 Cox Survey

DRIVING DIRECTIONS TO MOBILE HOME Hwy 47 South to Rusty's
#5801 SW SR 47

Back door is unlocked

MOBILE HOME INSTALLER Rusty Knowles PHONE 386-755-6441 CELL 386-347-0886

MOBILE HOME INFORMATION

MAKE Fleetwood YEAR 93 SIZE 14 X 70 COLOR gray

SERIAL No. GAFLP75A18513WE

WIND ZONE II Must be wind zone II or higher NO WIND ZONE I ALLOWED

INSPECTION STANDARDS

INTERIOR:

(P or F) - P= PASS F= FAILED

☒ SMOKE DETECTOR () OPERATIONAL () MISSING

☒ FLOORS () SOLID () WEAK () HOLES DAMAGED LOCATION

☒ DOORS () OPERABLE () DAMAGED

☒ WALLS () SOLID () STRUCTURALLY UNSOUND

☒ WINDOWS () OPERABLE () INOPERABLE

☒ PLUMBING FIXTURES () OPERABLE () INOPERABLE () MISSING

☒ CEILING () SOLID () HOLES () LEAKS APPARENT

☒ ELECTRICAL (FIXTURES/OUTLETS) () OPERABLE () EXPOSED WIRING () OUTLET COVERS MISSING () LIGHT
FIXTURES MISSING

EXTERIOR:

☒ WALLS / SIDING () LOOSE SIDING () STRUCTURALLY UNSOUND () NOT WEATHERTIGHT () NEEDS CLEANING

☒ WINDOWS () CRACKED/ BROKEN GLASS () SCREENS MISSING () WEATHERTIGHT


☒ ROOF () APPEARS SOLID () DAMAGED

STATUS

APPROVED ☒ WITH CONDITIONS:

NOT APPROVED NEED RE-INSPECTION FOR FOLLOWING CONDITIONS

SIGNATURE



ID NUMBER

302

DATE

8/2/12